# Oil Field Environmental Incident Summary

**Responsible Party:** FLATLAND RESOURCES II, LLC **Well Operator:** FLATLAND RESOURCES II, LLC

Well Name: FETTIG SWD 1

Field Name: CORRAL CREEK Well File #: 90295

Date Incident:7/14/2014Time Incident:06:15Facility ID Number:County:DUNNTwp: 147Rng: 95Sec: 10Qtr:

Location Description:

Submitted By: Joseph Eriksen Received By:

Contact Person: Sean Pask

235 E LAKE ST

WAYZATA, MN 55391

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1 Mile

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Yes - On Facility Site Reported to NRC: Unknown

Spilled Units Recovered Units Followup Units

Oil

Brine 100 Barrels 50 Barrels 50 barrels

Other

Description of Other Released Contaminant:

None

Inspected: Written Report Received: 1/16/2017 Clean Up Concluded: 7/14/2014

Risk Evaluation:

None

Areal Extent:

## Potential Environmental Impacts:

None

#### Action Taken or Planned:

The spill was contained on the site by the containment berm. The area was coned off and a vac truck from Bear Mountain LLC that was onsite was used to suck up the fluid. Flatland Solutions Operations Manager and Cypress Energy Partners General Manager were notified. Absorbent & Safety Solutions was notified to remove/replace the rock/dirt.

Wastes Disposal Location: Approximately 50 bbls. of fluid was recovered and disposed of on site

through the disposal. The solids were removed and replaced by Absorbent &Safety Solutions and disposed of at Indian Hills Disposal in

Williston, ND.

Agencies Involved:

### **Updates**

Date: 7/17/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

#### Notes.

Release, due to unspecified cause, remained on location within the diking, according to the report. NDIC retains oversight.